



SolderLab Inc.  
12675 Danielson Court #403  
Poway, CA 92064  
EIN: # 811543016

(858) 225-8626  
Fax: (858)225-1881  
www.solderlab.com  
sales@solderlab.com

## YOUR QUOTE


Quote Number SL-0104190005

Item	Description	Unit Cost	Quantity	Line Total
FT-Urgent	Flex Test - URGENT Immediate Test Results	\$195.00	1	\$195.00

### Terms

SolderLab automatically extends Net 30 Terms to all domestic purchases. Purchase Orders are welcome and can be faxed to (858) 225-1881 or emailed to sales@solderlab.com. We also accept all major credit cards over the phone or online.

SolderLab Welcomes all Major Credit Cards.



## Certificate of Analysis

**Solder Sample Data**

Sample ID # SN63 PB 37 Alpha  
 Alloy ID # Leaded  
 Machine ID # Wave Solder 1

**Customer Order Information**

Company: Company XYZ  
 Contact: Frank  
 Email: frank@xyz.com  
 PC: 12345

Sn63Pb37		Sn63	Pb37	Impurities											
Your Solder Sample	Sn%	Pb%	Ag%	Cu%	Sb%	As%	Bi%	Cd%	In%	Al%	Fe%	Ni%	Zn%	Au%	
Ø	63.00	36.90	0.0000	0.3010	0.1000	0.0100	0.0000	0.0052	0.0040	0.0030	0.0100	0.0050	0.0010	0.0250	
Unit	Wt %	Wt %	Wt %	Wt %	Wt %	Wt %	Wt %	Wt %	Wt %	Wt %	Wt %	Wt %	Wt %	Wt %	
Alloy Health	63.000	36.900	●	◆	●	●	◆	●	●	●	●	▲	●	●	
Comments	In Spec.	In Spec.	In Spec.	Out of Spec.	In Spec.	In Spec.	In Spec.	Out of Spec.	In Spec.	In Spec.	In Spec.	Warning	In Spec.	In Spec.	
* IPC Limits	Sn%	Pb%	Ag%	Cu%	Sb%	As%	Bi%	Cd%	In%	Al%	Fe%	Ni%	Zn%	Au%	
HI = 63.5															
LO = 62.5				0.3000	0.5000	0.0300	0.2500	0.0050	0.0060	0.0200	0.0100	0.0050	0.2000	0.4000	

IMMEDIATE TEST SOLDER

# URGENT